

FITNESS CERTIFICATE


[To be filled in by the Inspecting Officer]
(Junior Engineer)

- Name of the Officer: Sheejamol Joseph,
Assistant Engineer, Elikkulam C.P.
2. Name of School: Jyothi Public School Paika
3. Location with name of Education Dist./Sub. Dist.: Paika, Ponkannam, Kanjireppally
4. Classification of buildings as specified in column 4 of the application for fitness certificate and size: Permanent multistoried RCC Framed structure, wall height - 3.70m
Ground Floor - 2 x 63.60 x 8.80 m
2 x 21.40 x 8.60 m
1 x 21.40 x 10.50 m
5. Period for which the certificate is issued: - 2021-2022
1st Floor - Same area as Ground Floor
11th Floor - "
6. Name of defect if any
- a) Foundation and Basement
 - b) Superstructure
 - c) Doors and windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks etc)
7. Any major defects noticed which will render the building unsafe in any manner: No
8. Whether maintenance works have been done properly: Yes
9. Whether the structure is sound or not for conducting classes: Sound only under normal weather condition

- Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 24/6/2021..... and found to be fit/unfit to conduct classes for the period..... 2021-2022..... for the reasons stated above.

Place..... Elikkulam.....
24/6/2021



Signature

Assistant Engineer
L.S.G.D. Section
Elikkulam Grama Panchayath